

**From:** [Howard, MarkW](#)  
**To:** [Moore, Gary](#)  
**Cc:** [Swackhammer, J-Troy](#)  
**Subject:** RE: API 653?  
**Date:** Tuesday, April 02, 2013 3:39:07 PM

---

I don't believe 653 addresses this issue.

Mark W. Howard  
SPCC Team Lead  
USEPA  
Office of Emergency Management  
Ariel Rios Building (Mail Code 5104A)  
1200 Pennsylvania Ave., N.W.  
Washington, DC 20460  
Email: [howard.markw@epa.gov](mailto:howard.markw@epa.gov)  
202-564-1964 Work  
202-412-1836 Cell

---

**From:** Moore, Gary  
**Sent:** Tuesday, April 02, 2013 4:12 PM  
**To:** Howard, MarkW  
**Subject:** API 653?

**Mark:**

**I need to know if 653 covers the removal of contaminated soils beneath a compromised tank bottom along with the installation of a liner covered by sand filler as a base for the tank. I suspect the materials below the tank have been contaminated and it is my understanding that there is no liner to prevent ground water contamination.**

**Thanks**

**Gary Moore**  
Federal On-Scene Coordinator  
U.S. EPA Region 6  
214-789-1627 cell  
214-665-6609 office  
[moore.gary@epa.gov](mailto:moore.gary@epa.gov)



9568191